


Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-268	Smoke	9/2/2009	ADS/TM	S11MM1029MH	Dry	Yes	802.14



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-268	Smoke	9/2/2009	ADS/TM	S11MM1029MH	Dry	Yes	802.14

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S11001012G1	S11001012MH	S11MM1029MH	148.841	8
S11MM1003G1	S11MM1003MH	S11MM1029MH	109.246	8
S11MM1029G1	S11MM1029MH	S11MM1002MH	252.063	8
S11MM1002G1	S11MM1002MH	S11MM1011MH	157.991	8
S11MM1019G1	S11MM1019MH	S11MM1002MH	133.998	8

Observations & Photos

Obs_ID S1028-268-OB01

Address 4734 Pimlico Rd

Status Private

Source Cleanout

Location Yard - back

Nearest MH S11MM1029MH

Comments Smoke from cleanout in back yard. 4734 Pimlico Rd.



Picture \S1028-268-OB01-P01.jpg

Comments Back of house, 4734 Pimlico Rd.

Obs_ID S1028-268-OB02

Address 3003 Woodland Ave


Status Private

Source Cleanout

Location Field / woods

Nearest MH S11001012MH

Comments Smoke from cleanout in empty lot. 3003 Woodland Ave.



Picture \S1028-268-OB02-P01.jpg

Comments Back of lot, 3003 Woodland Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-268	Smoke	9/2/2009	ADS/TM	S11MM1029MH	Dry	Yes	802.14

Obs_ID S1028-268-OB03

Address 3005 Woodland Ave


Status Private

Source Cleanout

Location Field / woods

Nearest MH S11001012MH

Comments Smoke from cleanout in empty lot. 3005 Woodland Ave.



Picture \S1028-268-OB03-P01.jpg

Comments Back of lot, 3005 Woodland Ave.

Obs_ID S1028-268-OB05

Address 4721 Delaware Ave


Status Private

Source Cleanout

Location Field / woods

Nearest MH S11MM1029MH

Comments Smoke from cleanout in empty lot. 4721 Delaware Ave.



Picture \S1028-268-OB05-P01.jpg

Comments Back of lot, 4721 Delaware Ave.

Obs_ID S1028-268-OB04

Address 4722 Pimlico Rd


Status Private

Source Service Lateral

Location Yard - back

Nearest MH S11MM1029MH

Comments Smoke from service lateral in back yard. 4722 Pimlico Rd.



Picture \S1028-268-OB04-P01.jpg

Comments Back of house, 4722 Pimlico Rd.

Obs_ID S1028-268-OB06

Address 4709 Delaware Ave

Status Private

Source Cleanout

Location Field / woods

Nearest MH S11MM1002MH

Comments Smoke from cleanout in empty lot. 4709 Delaware Ave.



Picture \S1028-268-OB06-P01.jpg

Comments Back of lot, 4709 Delaware Ave.

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-268	Smoke	9/2/2009	ADS/TM	S11MM1029MH	Dry	Yes	802.14

Obs_ID S1028-268-OB07

Address 3114 Virginia Ave


Status Private

Source Service Lateral

Location Paved other

Nearest MH S11MM1002MH

Comments Smoke from service lateral in paved area behind house. 3114 Virginia Ave.



Picture \S1028-268-OB07-P01.jpg

Comments Back yard, 3114 Virginia Ave.

Obs_ID S1028-268-OB09

Address 3122 Virginia Ave

Status Private

Source Cleanout

Location Yard - back

Nearest MH S11MM1002MH

Comments Smoke from cleanout in back yard. 3122 Virginia Ave.



Picture \S1028-268-OB09-P01.jpg

Comments Back of house, 3122 Virginia Ave.

Obs_ID S1028-268-OB08

Address 3102 Virginia Ave


Status Private

Source Cleanout

Location Paved concrete

Nearest MH S11MM1019MH

Comments Smoke from cleanout in paved concrete behind house. 3102 Virginia Ave.



Picture \S1028-268-OB08-P01.jpg

Comments Back of house, 3102 Virginia Ave.